



Conventional current flow:

Left Hand Rule for Motors



Thumb = Motion
First Finger = Field
Second Finger = Current (+ve to -ve)

Right hand Rule for Generators



Thumb = Motion
First Finger = Field
Second Finger = Current (+ve to -ve)